

DORMAN®

NEW SINCE 1918

www.DormanProducts.com

FORMERLY "DEALER ONLY" PARTS

Now Available from Aftermarket

AUGUST/SEPTEMBER 2013

Steel Wheels

Comprehensive program of Direct-Fit Replacement Wheels

- Fully compatible with original wheel covers and all TPMS sensors
- Dorman's Steel Wheels adhere to DOT standards

939-151
Mitsubishi Galant
2012-04
Pop Code: W
VIO: 193,685



DIRECT FIT
REPLACEMENTS

FEATURED CATEGORY

19 TOTAL SKUs!

Provide Coverage for over 8.5 Million Vehicles on the Road Today

Failure Mode:

- Replaced due to damage associated with pot holes, curb rash and collisions
- Failure results in wheel vibration and/or a flat tire

Third Brake Lamps

In many states, just one dark LED bulb results in failed inspection

18 TOTAL SKUs AVAILABLE!



923-228
Mini Cooper
2006-02
Pop Code: C
VIO: 165,548

ALSO AVAILABLE:

923-225
Ford Escape 2012-08,
Ford Explorer 2012-02,
Mercury Mariner 2011-05,
Mercury Mountaineer
2010-02
Pop Code: D
VIO: 3,248,490


Failure Mode:

- LED unit burns out over time due to normal wear and tear
- Water intrusion or breakage

Radio Power Supply Board

NEW TO THE AFTERMARKET

Provides power and restores functionality to radio LCD screen



586-001
Ford 2005-98, Mazda 2003-99, Mercury 2001-98
Pop Code: C
VIO: 6,867,033

Failure Mode:

- Electrical failure
- Failure results in dark LCD display on radio

Tailgate Glass Hinges

NEW TO THE AFTERMARKET

Includes two hinges



924-160
Ford Explorer,
Mercury Mountaineer
2005-02
Pop Code: C
VIO: 1,399,384

Failure Mode:

- Rust
- Corrosion
- Failure results in difficulty opening and closing tailgate

Thermostat Housing Kit

LINE EXTENSION

Complete assembly housing for easy installation



902-200
Contour, Cougar, Escort,
Focus, Mystique
2004-99
Pop Code: B
VIO: 790,087

Failure Mode:

- Plastic becomes brittle and cracks
- Failure results in coolant leaks

Water Outlets

LINE EXTENSION

Complete assembly housing for easy installation



902-210
Ford Mustang
2010-05
Pop Code: C
VIO: 353,998

Failure Mode:

- Plastic becomes brittle and breaks
- Failure results in coolant leaks

ALSO AVAILABLE:

902-920
Audi 2009-04,
Volkswagen 2008-07,
Volkswagen 2005-99
Pop Code: C
VIO: 186,579

BE THE FIRST TO KNOW ABOUT FORMERLY "DEALER ONLY" PARTS!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492

DORMAN®

NEW SINCE 1918

www.DormanProducts.com

FORMERLY "DEALER ONLY" PARTS

Now Available from Aftermarket

AUGUST/SEPTEMBER 2013

Transmission Filler Cap Lock Pin

**NEW TO THE
AFTERMARKET**

Locks transmission dipstick tube



917-299
Mercedes-Benz
2012-98
Pop Code: D
VIO: 1,900,112

Failure Mode:

- Often breaks when servicing or checking the transmission fluid

Keyless Entry Remotes

LINE EXTENSION

Easy to Program - No special tools required

Programming Instructions included

**15 TOTAL SKUs
AVAILABLE!**



13721
Chevrolet, GMC
2012-08

Pop Code: D
VIO: 370,715

Scan QR code to
view Keyless Remote
video or visit
[www.YouTube.com/
DormanProducts](http://www.YouTube.com/DormanProducts)



Failure Mode:

- Circuit board breaks
- Broken or lost

Door Lock Actuator

LINE EXTENSION

746-015
Cadillac 2006-02,
Chevrolet, GMC 2006-00
Pop Code: C
VIO: 270,2851



Failure Mode:

- Electrical failure
- Seizing from extreme weather
- Electrical contact corrosion

Steering Shaft

LINE EXTENSION



Double-D design provides
improved durability and
eliminates clunking



425-465
Lexus ES350,
Toyota Camry
2011-07
Pop Code: D
VIO: 2,286,125

Failure Mode:


- Clunking and/or binding
- Failure results in the inability to steer the vehicle properly

Sliding Door Rollers

LINE EXTENSION

Restores door to proper function

924-910
Caravan, Town & Country,
Voyager
2008-01
Pop Code: C
VIO: 2,696,873



Failure Mode:

- Fails due to continued use
- Rollers wear over time and cause door to come off the track and misalign

ALSO AVAILABLE:

924-125
Buick 2007-05,
Chevrolet 2009-97,
Oldsmobile 2004-97,
Pontiac 2005-99
Pop Code: D
VIO: 1,189,808

Radiator Bushings

LINE EXTENSION

Secures radiator to vehicle



924-425
Infiniti 2004-96,
Nissan 2002-90
Pop Code: C
VIO: 1,655,266

Failure Mode:

- Rubber bushings dry rot over time due to the elements

BE THE FIRST TO KNOW ABOUT FORMERLY "DEALER ONLY" PARTS!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492

AUGUST/SEPTEMBER 2013

Exhaust Manifold Kits

LINE EXTENSION



Includes gaskets and hardware for a complete installation

372 TOTAL SKUs AVAILABLE!



674-970
Ford
2010-08
Pop Code: D
VIO: 260,014

ALSO AVAILABLE:

674-909
Chrysler 2007,
Dodge 2007-04,
Mitsubishi 2007-06
Pop Code: D
VIO: 599,247

Failure Mode:

- Original unit warps and cracks
- Failure causes exhaust leaks


Shift Park Release Link

LINE EXTENSION

Connects the Shifter Knob Button to the interlock mechanism



Reduce Repair Cost -
Replace just the failed Link instead of the Entire Shifter Assembly



924-738
Jeep Wrangler
2002-97

Pop Code: D
VIO: 456,358

Failure Mode:

- Plastic linkage breaks over time
- Failure results in inability to shift out of park

Shift Bushings

LINE EXTENSION



905-107
Ford 2012-90,
Lincoln 2004-90,
Mercury 2007-90
Pop Code: C
VIO: 23,152,314

Failure Mode:

- Failure results in difficulty shifting
- Wear and tear

Hood Release Cables

LINE EXTENSION

64 TOTAL SKUs AVAILABLE!



912-079
Jeep Grand Cherokee
2004-99

Pop Code: D
VIO: 1,208,386

Sway Bar Kit

LINE EXTENSION



Includes mounting bolts for a complete repair



RUST

927-110
Buick 2009-97,
Chevrolet 2011-00,
Oldsmobile 2002-98,
Pontiac 2008-97
Pop Code: C
VIO: 5,326,826

Failure Mode:

- Rust and corrosion
- Failure causes the suspension to become unstable


Shift Indicator Bracket

LINE EXTENSION

Holds Shift Indicator cable to steering column



Reduce Repair Cost -
Replace just the failed bracket, not the entire Shift Indicator Assembly



83244
Ford 2005-99,
Lincoln 2002-99
Pop Code: D
VIO: 3,068,350

Failure Mode:

- Cracks and breaks
- Failure results in gear indicator not properly indicating selected gear

Windshield Washer Grommets

LINE EXTENSION

Seals level sensor and washer reservoir



49458
Washer Fluid
Reservoirs Grommet
Chrysler 2010-07, Dodge 2010-06, Jeep, Ram 2011
Pop Code: C
VIO: 2,272,072

Failure Mode:

- Grommet becomes brittle over time
- Failure results in washer fluid leaks



49459
Washer Pump Grommet
Chrysler, Dodge 2011-07,
Jeep 2011-05, Ram 2011
Pop Code: C
VIO: 4,101,429